



P.O. Box 1089 Coldspring Tx 77331
 Website: eastexlabs.com
 Email: eastexlab@eastex.net
 Tel: 936 653 3249



Galveston County MUD 12
 Benry Utilities
 13735 Grant Rd
 Cyoress, TX 77410

LABORATORY ANALYTICAL REPORT

Project: GC MUD 12 Effluent before Weir

Sample Site:	Before Weir	Sample Number:	4470661-01	Collector:	CSW
Sample Type:	Grab			Sampled:	11/18/2024 10:15
Sample Matrix:	Water			Received:	11/18/2024 13:45
Client Matrix:	Water				

Analyte	Result	Reporting Limit	Units	Nelac Status	Batch	Analyzed	Analyst	Method	Notes
Enterococcus	344	1	mpn/100ml	A	B4K2468	11/18/2024 14:26	MEB	Enterolert IDEXX	
TSS	60.7	1.0	mg/L	A	B4K2432	11/19/2024 11:07	SEJ	SM 2540 D	

SM 2540 D - Quality Control Eastex Environmental Laboratory - Coldspring

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch B4K2432 - No Prep										
Blank (B4K2432-BLK1) Prepared & Analyzed: 11/19/24										
TSS	ND	1.0	mg/L							
Duplicate (B4K2432-DUP1) Source: 4470058-01 Prepared & Analyzed: 11/19/24										
TSS	112	1.0	mg/L		103			8.37	10	
Batch B4K2468 - No Prep Micro										
Blank (B4K2468-BLK1) Prepared & Analyzed: 11/18/24										
Enterococcus	ND	1	mpn/100ml							
Duplicate (B4K2468-DUP1) Source: 4470013-17 Prepared & Analyzed: 11/18/24										
Enterococcus	ND	10	mpn/100ml		20				200	

Daniel Bowen

Daniel Bowen, Chief Operations Officer

Qualifiers

DRAFT REPORT

The results in this report apply to the samples analyzed in accordance with the chain of custody document.
 This analytical report must be reproduced in its entirety. Alkalinity titrated to pH 4.5 endpoint.